



Bearing Installation Instructions

Bearing

Installation instructions

To avoid damages during the wheel bearing assembly please be aware:


- For mounting no mechanical force may be applied.
- When assembling the bearings, make sure that the wheel bearing is not tilted.
- If necessary, special assembly tools should be used.
- The improper use of an impact tool such as hammer should be avoided.

Much of the premature bearing failures could be prevented by a professional installation!

Installation instructions

Causes of damages during the wheel bearing assembly:


- Hitting the inner ring



Installation instructions

Causes of damages during the wheel bearing assembly

Residues in the bearing seat can cause the disturbance in the functionality of axes;
As a result there might be punctual overloading / peeling.




Installation instructions

Causes of damages during the wheel bearing assembly

Mounting going over the inner ring.


The result here is an overload of the contact surfaces.
Damage is peeling at rolling element.



Installation instructions

Causes of damages during the wheel bearing assembly


Too small an amount or unsuitable lubricant leads to overheating of the bearing components.



Installation instructions


Causes of damages during the wheel bearing assembly

Too high start torque effect which causes the overheating of the bearing components




Installation instructions

Loose meshing engagement



Installation instructions

Loose meshing engagement



Installation instructions

Loose meshing engagement

Affected vehicles

Volvo 850, C70, S70, V70

Problem:

Vibrations and cracking noises in the front area of the axle.

Cause:

After re joint drive shaft without glue remained minimal clearance between the wheel hub gearing and joint shaft.

Remedy

Glue the hub with a suitable metal adhesive –
e.g. Volvo.




Damages:

Shelling

is a result of an edge load for tapered roller bearings

- Disruption of functional axes
- Excessive tightening torque




Advanced hulling to
edge loads

Damages


Flattening

is a result of jamming

- Residues in the wheel bearing housing
- Damage to the wheel bearing housing / hub
- Chips, dirt particles between outer ring and housing



radial load
(Oval jammed
rings)



Impression of a chip
and corresponding
peeling worse as a
result circulation in
housing

Starmann[®]

GERMANY AUTOTEILE

Damages

Corrosion



Starmann[®]

GERMANY AUTOTEILE

Damages

Corrosion



Damages


Corrosion



Damages

Corrosion

Damage to the wheel hub will destroy the seal.



Starmann®

GERMANY AUTOTEILE

Damages

Corrosion (RS-1027)


Audi A1/A2,
VW Polo 9N
T5 / Tuareg etc.



Damages

Sounds


Peeling the roll body distance
Overload of the inner ring
Hitting marks to the inner ring



Damages


Sounds

Indentations on the running surface of the
outer ring



Damages

Failure after a short running time



Flattening in the bearing housing

Flattening



Separate lanes at the tread


Damages

Failure after a short running time



Damages


Failure after a short running time



Damages

Failure after a short running time


Bearing preload too low



Damages

Bearing preload too low

Failure after a short running time



Damages

Failure after a short running time

Bearing preload too high




Tips and tricks

Tightening torque

Ford Fiesta div.

axle nut
tightening torque
235 nm




Tips and tricks

Choose correct wheel bearing play

Adjust the wheel bearing loose in accordance with the manufacturer's instructions.

e.g. W203

Wheel bearing clearance 0.01 - 0.02mm



Tips and tricks

Correct mounting (RS-1027)

Not mounted using the appropriate tool!


Audi A1/A2,
VW Polo 9N
T5 / Tuareg etc.



Tips and tricks

Correct mounting (RS-1027)

Audi A1/A2,
VW Polo 9N
T5 / Tuareg etc.



Tips and tricks

Correct mounting (RS-1027)

The wheel bearing was fitted correctly!

Audi A1/A2,
VW Polo 9N
T5 / Tuareg etc.




Hub

Check the runout of the wheel hub

Excessive hub shock caused:

- Noise
- Flapping
- Unequal pad wear
- Poor braking action




Check the runout of the wheel hub according to the manufacturer's instructions!

Hub

Check the runout of the wheel hub

Excessive hub shock caused:

- Noise
- Flapping
- Unequal pad wear
- Poor braking action



Check the runout of the wheel hub according to the manufacturer's instructions!



Thank you for Your
attention!